

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014142**Date Inspected:** 01-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai,China

CWI Name:	Mr.An Qing Xiang/Mr.You Qi Gu			CWI Present:	Yes	No	
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006			Component:	Tower		

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Nagalingam Pandaram Pillai was present during the times noted above for observations relative to the work being performed.

Magnetic Particle Testing:-

TOWER TRAIL ASSEMBLY AREA:-

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an MT report for this date. The member is identified as East, West Tower Façade Connection Plates. The weld designations reviewed are as follows:-

ESD1-SA237E/F-4

ESD1-SA227C/H-63

ESD1-SA296A/E2,4

WSD1-SA653E/F-4

IN PROCESS INSPECTION:-

TOWER TRAIL ASSEMBLY AREA:-

This QA inspector observed the following work in progress:

FCAW welding of weld joint no: ESD1-A167A/H-8B located on Shear Splice Plate. Welder is identified as

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

040367.ZPMC QC is identified as Mr. Fu Wei Min. The welding variables recorded by QC appeared to comply with the WPS-B-T-2233-TC-U5-F.

This QA inspector observed the following work in progress:

FCAW welding of weld joint no: NSD1-A112A/H-3B located on Shear Splice Plate. Welder is identified as 057244.ZPMC QC is identified as Mr. Fu Wei Min. The welding variables recorded by QC appeared to comply with the WPS-B-T-2233-TC-U5-F.

BAY #11:-

This QA inspector observed the following work in progress:

SMAW welding of weld joint no: ED1-STSA4-6-135M-1-10B located on Strut Plate. Welder is identified as 044541.ZPMC QC is identified as Mr.Xu Jin Long. The welding variables recorded by QC appeared to comply with the WPS-B-T-2212-TC-U5b.

This QA inspector observed the following work in progress:

SMAW welding of weld joint no: ED1-STSA4-6-139M-2-74B located on Strut Plate. Welder is identified as 041271.ZPMC QC is identified as Mr.Xu Jin Long. The welding variables recorded by QC appeared to comply with the WPS-B-T-3212-TC-U5b-1.

This QA inspector observed the following work in progress:

SMAW welding of weld joint no: ESD1-TL5-2B/F-35B located on East Lift 5 Grillage Plate. Welder is identified as 040690.ZPMC CWI is identified as Mr.An Qing Xiang. The welding variables recorded by QC appeared to comply with the WPS-B-T-3213-B-U3-b.

Unless otherwise noted, all work observed on this date appeared to generally comply with the applicable contract documents.



Summary of Conversations:

No Relevant Conversation.

Comments

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Skyler Guest - 15000422360, who represents the Office of Structural Materials for your project.

Inspected By:	Pillai,Pandaram	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
